

MEGNEVEZÉS	GYÁRTMÁNY	MENNY.	M.E.	NETTÓ ÁR/DB
1207 ETN9	SKF	4	DB	4700.-
1207 KC3	SKF	5	DB	4700.-
1211 ETN9	SKF	2	DB	4368.-
1315	SKF	1	DB	20160.-
1726204-2RS1	SKF	4	DB	1500.-
21306 CC	SKF	1	DB	7400.-
21314	SKF	2	DB	9900.-
21314 CC	SKF	1	DB	15000.-
21319 E	SKF	1	DB	34000.-
2203 E-2RS1/TN9	SKF	9	DB	1900.-
2206 E-2RS1/TN9	SKF	6	DB	2500.-
22209 CC	SKF	1	DB	6700.-
22211 E	SKF	1	DB	7600.-
22211 ETN9	SKF	1	DB	7600.-
22212 CCK	SKF	6	DB	10000.-
22214 CKJ	SKF	1	DB	11000.-
22216 CCK	SKF	1	DB	13000.-
22232 K	SKF	1	DB	110000.-
22314 EK	SKF	4	DB	17000.-
22340 CC W33	SKF	1	DB	520000.-
22340CCK/W33 W49ZEXPLORER	SKF	2	DB	490000.-
23222 CCK/W33	SKF	2	DB	40000.-
23228 CC/W33	SKF	1	DB	98000.-
23232 CCKW33	SKF	2	DB	148000.-
234418 TN9/SP	SKF	6	DB	80000.-
30212 J2/Q	SKF	2	DB	4200.-
30312 J2/Q	SKF	2	DB	8200.-
31316 J1/QCL7A	SKF	2	DB	22000.-
32006 X/Q	SKF	1	DB	2500.-
3211 A	SKF	8	DB	7200.-
32208 J2/Q	SKF	6	DB	2500.-
32309 J2/Q	SKF	4	DB	5500.-
3309	SKF	2	DB	11200.-
4212 ATN9	SKF	5	DB	9000.-
51213	SKF	1	DB	4400.-
51234 M	SKF	1	DB	70000.-
51410	SKF	1	DB	10000.-
6005 2Z	SKF	7	DB	510.-
61808-2RS1	SKF	19	DB	2400.-
61903-2RS1	SKF	2	DB	1000.-
6207 2Z	SKF	1	DB	1800.-
6209 2Z	SKF	1	DB	2800.-
6213 2RS1/C3	SKF	16	DB	4100.-
6213 2Z	SKF	3	DB	4100.-
6217 C4	SKF	9	DB	10900.-
6218 C3	SKF	5	DB	12000.-
6219	SKF	2	DB	12000.-
6224	SKF	1	DB	21000.-
62309 2RS1	SKF	12	DB	6000.-
6300 2Z	SKF	1	DB	300.-
6315	SKF	2	DB	9500.-
6316 C3	SKF	4	DB	12400.-
6316 2RS1	SKF	2	DB	12400.-
6316 2RS1/C3	SKF	2	DB	12400.-
6316 2Z/C3	SKF	6	DB	12400.-
6316 2Z	SKF	1	DB	16500.-

6317 2RS1	SKF	1	DB	18500.-
6409	SKF	3	DB	7000.-
6414	SKF	2	DB	22000.-
7012 C/P4	SKF	2	DB	11500.-
7303 BEP	SKF	8	DB	1500.-
7307 BEP	SKF	8	DB	2500.-
7313 BEP	SKF	1	DB	12000.-
7316 BM	SKF	1	DB	25000.-
AH 2340 HÜVELY	SKF	1	DB	60000.-
C 2320 K	SKF	1	DB	55000.-
GE 50ES	SKF	1	DB	3800.-
GE 60 ES	SKF	2	DB	5700.-
GE 80ES 2RS	SKF	1	DB	15000.-
F 208	SKF	1	DB	1100.-
F 210	SKF	1	DB	1500.-
FY 509 M	SKF	2	DB	1500.-
H 2314	SKF	4	DB	3600.-
H 2324	SKF	1	DB	15000.-
H 2340 KOMPLETT	SKF	1	DB	38000.-
HJ 1034	SKF	2	DB	32000.-
HJ 240 EC	SKF	1	DB	85000.-
HK 0306	SKF	21	DB	300.-
HK 1212	SKF	9	DB	350.-
HK 3518 RS	SKF	14	DB	750.-
KM 8	SKF	10	DB	390.-
KM 14	SKF	4	DB	1100.-
LBAS 25	SKF	6	DB	3500.-
LBBR 20-2LS	SKF	2	DB	3500.-
LBBR 40-2LS	SKF	6	DB	6500.-
LBCD 12-2LS	SKF	5	DB	3200.-
LBCD 16-2LS	SKF	7	DB	3300.-
LBCD 25 A-2LS	SKF	16	DB	3400.-
LBCF 25-2LS	SKF	21	DB	3400.-
LBCR 25 A-2LS	SKF	24	DB	3300.-
LHCR 12 Z	SKF	3	DB	3000.-
MB 8	SKF	5	DB	100.-
MB 25	SKF	2	DB	900.-
MB 34	SKF	1	DB	2900.-
MB 36	SKF	1	DB	3000.-
MB 52	SKF	5	DB	9900.-
N 316 ECM	SKF	3	DB	31000.-
NA 4901	SKF	3	DB	2000.-
NJ 205 ECP	SKF	6	DB	2200.-
NJ 2209 ECJ/C3	SKF	1	DB	6000.-
NJ 2305 ECP	SKF	1	DB	4600.-
NJ 312 ECJ	SKF	4	DB	11000.-
NJ 314 ECP	SKF	1	DB	18000.-
NJ 316 ECM/C4WA301	SKF	1	DB	45000.-
NJ 316 ECP	SKF	1	DB	21000.-
NJ 324 ECM/C3	SKF	1	DB	105000.-
NK 19/16	SKF	17	DB	800.-
NK 68/35	SKF	8	DB	3200.-
NN 3020 K/SPW33	SKF	1	DB	70000.-
NU 218 ECML/C3B20	SKF	2	DB	27000.-
NU 2208 ECP	SKF	4	DB	4100.-
NU 2213 ECP	SKF	1	DB	13000.-
NU 2314 ECML	SKF	5	DB	26000.-
NU 407	SKF	2	DB	10000.-

NU 410/C4	SKF	2	DB	15000.-	
NUP 207 ECP	SKF	2	DB	3800.-	
NUP 208 ECP	SKF	4	DB	6000.-	
NUP 2206 ECP	SKF	3	DB	5600.-	
PCMF 121412B	SKF	13	DB	500.-	
SNL 532	SKF	1	DB	80000.-	
SY505M Komplett	SKF	3	DB	5500.-	FAG-INA
YET 206	SKF	1	DB	3000.-	
11205 TV	FAG	8	DB	2000.-	
1309 TV	FAG	2	DB	5000.-	
20211 K.MB.C3	FAG	1	DB	19000.-	
21310 B	FAG	8	DB	11800.-	
21318 E.TVPB	FAG	1	DB	25000.-	
2209 TV	FAG	2	DB	4000.-	
22209 E S	FAG	2	DB	7200.-	
22213 ESK.TVPB	FAG	1	DB	9000.-	
22214 K	FAG	1	DB	11000.-	
22217 E	FAG	4	DB	15800.-	
222-2214 / 22214 K	FAG	1	DB	11000.-	
22222 SKMB	FAG	2	DB	43000.-	
22238 MB	FAG	2	DB	170000.-	
22240-B-MB	FAG	2	DB	210000.-	
22316 HL K	FAG	1	DB	29500.-	
22326 ESK.TVPB	FAG	3	DB	105000.-	
22336 MB.C3	FAG	1	DB	260000.-	
22340 MB	FAG	1	DB	375000.-	
23028 ESK.TVPB	FAG	1	DB	38000.-	
23036 ESK.TVPB	FAG	1	DB	82000.-	
24126 ES.TVPB	FAG	1	DB	68000.-	
30311 A	FAG	5	DB	5500.-	
31307 CZ	FAG	8	DB	4000.-	
31308 A	FAG	2	DB	4100.-	
32211 A	FAG	4	DB	4100.-	
32309 A	FAG	4	DB	5500.-	
3313	FAG	1	DB	6700.-	
3314	FAG	1	DB	8200.-	
491950076 30222 A 1 PÁR KÖZGYŰRŰVEL	FAG	1	DB	35000.-	
51105	FAG	1	DB	800.-	
51113	FAG	2	DB	3000.-	
51216	FAG	1	DB	4200.-	
53218	FAG	2	DB	13000.-	
53310 B	FAG	2	DB	7500.-	
53312	FAG	5	DB	10000.-	
6012 1K	FAG	6	DB	1500.-	
6213 1K	FAG	5	DB	3900.-	
6222 C4 F3	FAG	1	DB	21000.-	
6226 MAC3	FAG	3	DB	50000.-	
6316 M.P64	FAG	2	DB	15000.-	
6316 2RSR	FAG	3	DB	11400.-	
6316 2ZR	FAG	1	DB	11400.-	
6319 2ZR	FAG	5	DB	18000.-	
6319 2ZR.C3	FAG	4	DB	22000.-	
6320 MAC3	FAG	2	DB	48000.-	
6410 C3	FAG	20	DB	8000.-	
6416 M.C3	FAG	12	DB	38000.-	
AHX 3126	FAG	1	DB	10500.-	
AHX 3128	FAG	2	DB	19000.-	

HJ 2322 E	FAG	1	DB	25000.-
KM 36	FAG	2	DB	3500.-
NA 49/22	FAG	6	DB	2000.-
NJ 216 EM1	FAG	2	DB	16000.-
NJ 310 E.TVP2	FAG	1	DB	7000.-
NJ 315 EM1C3	FAG	4	DB	42000.-
NJ 317 EM1C3	FAG	1	DB	49000.-
NJ 319 MC3	FAG	1	DB	52000.-
NU 220 E.TVP2	FAG	1	DB	15000.-
NU 2210 E.TVP2	FAG	5	DB	5000.-
NU 232 E.M1A.C3	FAG	3	DB	90000.-
NU 318 EM1AC3	FAG	3	DB	31000.-
NU 319 E.M1.C3	FAG	2	DB	49500.-
NU 319 ETVP2	FAG	2	DB	32000.-
NU 410 M1.C3	FAG	10	DB	12000.-
NU 414 M C4	FAG	1	DB	36000.-
QJ 232 N2 MPA	FAG	1	DB	133000.-
804772 BELSŐ GYŰRŰ	FAG	15	DB komplett	145000.-
32040 X KÜLSŐ GYŰRŰ	FAG	15	DB	
21314 E	NACHI	1	DB	16600.-
22230 EW33	NACHI	2	DB	59000.-
6207 Z	NACHI	2	DB	2100.-
6240	NACHI	1	DB	95000.-
6315 2NSL	NACHI	33	DB	9800.-
6316 2NS	NACHI	9	DB	10000.-
6317 2NSL	NACHI	6	DB	12000.-
6318	NACHI	1	DB	10000.-
6319 2NS	NACHI	8	DB	16500.-
6321 C3	NACHI	1	DB	28000.-
7212	NACHI	1	DB	2800.-
NU 313	NACHI	2	DB	8000.-
2207 ETNG	NSK	1	DB	1900.-
2213	NSK	2	DB	4300.-
22214 CDK	NSK	1	DB	7000.-
22219 EAE4	NSK	1	DB	12500.-
22320 EAE4	NSK	2	DB	43000.-
2310	NSK	2	DB	6500.-
24032 CE4S11	NSK	1	DB	82000.-
3211 J	NSK	2	DB	6900.-
3306	NSK	1	DB	3500.-
4212 BTNG	NSK	5	DB	8000.-
51234 X	NSK	1	DB	28600.-
52320	NSK	1	DB	53100.-
53310 U	NSK	1	DB	5000.-
6206	NSK	2	DB	500.-
6216 CM	NSK	1	DB	4000.-
6315 DDU AV2S	NSK	6	DB	9800.-
6316 2RS C3	NSK	1	DB	10000.-
6316 ZZ C3E AV2S	NSK	8	DB	10000.-
6319 C3E	NSK	2	DB	16500.-
6319 DDU AV2S	NSK	7	DB	16500.-
6409 AZZC3	NSK	7	DB	6600.-
HR 30313 J	NSK	2	DB	4000.-
HR 31314 JDF+KRCA130	NSK	2	DB	17000.-
HR 32320 J	NSK	2	DB	78000.-
NJ 314 W C3 *	NSK	2	DB	6700.-

NJ 315 W *	NSK	1	DB	11800.-
NU 220 W *	NSK	1	DB	15200.-
NU 220 W * 110Outer Ring ASS "Y	NSK	1	DB	15200.-
NUP 211W	NSK	2	DB	4500.-
53308 A	RIV	2	DB	3000.-
F-560572.32	INA	18	DB	1200.-
HK 2516.2RS	INA	24	DB	500.-
HK 2530 2RS	INA	8	DB	900.-
KR 19 PP A	INA	4	DB	3000.-
NA 4822	INA	1	DB	10000.-
ZKLN 1034.2RS PE	INA	6	DB	18000.-
21308 J	RHP	1	DB	4000.-
22211 EJW33	RHP	1	DB	4500.-
22217 EJW33	RHP	2	DB	8500.-
22324 EMW33	RHP	1	DB	55500.-
23026 JW33	RHP	1	DB	26000.-
23028 EJW33	RHP	1	DB	22500.-
7219 TDUEP3GV0/D	RHP	1	DB	7000.-
QJ 316 MB	RHP	1	DB	32000.-
22240 MBW33	ROLLWAY	2	DB	137000.-
32028 XA	ROLLWAY	2	DB	25000.-
NU 222 EM	ROLLWAY	1	DB	21100.-
21312 D1	NTN	1	DB	9000.-
4T-47820U3A KÜLSŐ GYŰRŰ	NTN	140	DB	3300.-
4T-47890U3A	NTN	116	DB	3300.-
4T-JLM710910PKU3A	NTN	138	DB	5600.-
4T-JLM710949PKU3A	NTN	140	DB	5600.-
22220 PC	KOYO	1	DB	13000.-
NU 2220	KOYO	2	DB	29500.-
NU 2226	KOYO	1	DB	32000.-
LBE 25 UU QP	IKO	8	DB	2500.-
LBE 40 UU	IKO	4	DB	3800.-
KBFC-30GUU	NIPPON	3	DB	3200.-
23234 CK MC3 W33	STEYR	1	DB	150000.-
4212 B/TG/MT2	STEYR	4	DB	6000.-
51218	STEYR	2	DB	10000.-
NJ 315 M/C3	STEYR	8	DB	29200.-
NU 216 P4	STEYR	1	DB	6000.-
NU 318	STEYR	1	DB	9000.-
NU 410 MC3ZS	STEYR	6	DB	10000.-
21310	HIC	7	DB	10800.-
1218 K	ZKL	1	DB	2200.-
1219	ZKL	5	DB	3000.-
1310	MGM	2	DB	980.-
1318 K	FLT	2	DB	7500.-

2216 K	ZKL	1	DB	2000.-
2218 K	ZKL	1	DB	3100.-
2219	ZKL	2	DB	4500.-
22216 K	ZKL	1	DB	4500.-
22217 W33J	ZKL	2	DB	5000.-
22312	ZKL	6	DB	3700.-
22319 W33M	ZKL	1	DB	13500.-
22328 KW33M	ZKL	1	DB	33000.-
23034	ZVZ	2	DB	16600.-
30310 A	MGM	2	DB	980.-
30313 A	ZVL	6	DB	1700.-
51411	ZKL	8	DB	3000.-
6005 ZZR	ZKL	1	DB	150.-
6016	MGM	3	DB	1200.-
6017 AZZ	ZKL	2	DB	1100.-
6034	ZVL	1	DB	7000.-
6210 A 2RS	ZKL	4	DB	700.-
6230	ZKL	7	DB	7100.-
6311	MGM	1	DB	900.-
6315 A2Z	ZKL	1	DB	2200.-
6315 ZZ	ZKL	1	DB	2200.-
NU 215 E	ZKL	3	DB	2500.-
NU 216	ZKL	2	DB	2200.-
NU 216 BNA	ZKL	1	DB	2200.-
NU/NJ 219 N NA	ZKL	2	DB	3500.-
NU/NJ 309 B NA	ZKL	3	DB	1400.-
NU/NJ 312	ZKL	1	DB	2200.-
NU 312 NA	ZKL	1	DB	3000.-
NU 318 MA C3 NA	ZKL	2	DB	7000.-
NU 318 NA	ZKL	1	DB	5700.-
NU 324 M C3 NA	ZKL	1	DB	17000.-
NU 2213	ZVL	1	DB	1300.-
NU 2216 BNA	ZKL	1	DB	3000.-
UR 7212 AA	ZKL	3	DB	1500.-

6-1000096	GPZ	3000	DB	500.-
F209	TR	1	DB	900.-
UCP 207	FK	2	DB	1500.-
6206 ZZ	CODEX	1	DB	1200.-
CSK12-M-C5	STIEBER	2	DB	3000.-